



Vehicle History Report (BC) #: 64586892
Report Date: September 24, 2025 | 2:41 p.m. EDT
Report Status: Complete

2011 HYUNDAI TUCSON GLS

Sport utility vehicle | 4 Cylinders | Gas
KM8JUCAC3BU273881
Country of Assembly: Korea (South)
Last Reported Odometer: 163,954 KM

Low
Kilometres™ >



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



9 Service Records Found



No U.S. History Found



5 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 24, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

KM8JUCAC3BU273881

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2016 Jul 18	British Columbia, Canada	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00
2017 Mar 12	British Columbia, Canada	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00
2018 Dec 20	British Columbia, Canada	
	Estimate: LEFT REAR SIDE Estimate Date: n/a	\$2,159.40
	Claim: COLLISION LEFT REAR SIDE	\$0.00
2024 Dec 2	British Columbia, Canada	
	Claim: COLLISION	\$0.00
2025 Mar 18	British Columbia, Canada	
	Estimate: LEFT REAR CORNER Estimate Date: n/a	\$5,332.81
	Claim: COLLISION LEFT REAR CORNER	\$5,012.27

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2022 Jan 22	British Columbia, Canada	
	Glass Record	\$726.42



Registration

✔ This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

KM8JUCAC3BU273881



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2011 Mar 31		Service Facility Maple Ridge, British Columbia, Canada	Vehicle serviced
2014 Mar 7	66,920 KM	Mobil 1 Lube Express Mission, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Air filter replaced Oil and filter changed
2014 Apr 30	72,065 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2014 May 21		West Coast Toyota Pitt Meadows, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Alignment performed Cabin air filter replaced/cleaned Fluids checked Four wheel alignment performed Oil and filter changed Safety inspection performed
2014 May 23	73,692 KM	Maple Ridge Hyundai Maple Ridge, British Columbia, Canada	Vehicle serviced
2014 May 29	73,864 KM	Service Facility Pitt Meadows, British Columbia, Canada	Vehicle serviced
2022 Aug 13	140,859 KM	Express Lube North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Fluids checked Oil and filter changed
2023 Aug 8	147,146 KM	Express Lube North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Fluids checked Oil and filter changed
2025 Sep 19	163,954 KM	Supertech Auto North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brake pads replaced Brake rotor(s) replaced Front brake pads replaced Rear brake pads replaced Rear brake rotor(s) replaced



Open Recalls

Recall #: R0152 | Leak - Engine Oil Pan Seal Recall Date: 2019 Jul 12

Recall Description

Issue: The engine oil pan seal could leak on some vehicles with a 2.4 L engine. If the leak is not repaired, over time this could lead to engine damage or an engine failure. An engine failure would cause a sudden loss of motive power with an inability to restart. Safety Risk: A sudden loss of motive power could increase the risk of a crash. In some cases, an engine failure may also result in a fire. Corrective Actions: The

company will notify owners by mail. Hyundai dealers will replace the vehicle's engine oil pressure switch with a new one. Dealers will also inspect the engine's oil pan, and if necessary, replace the oil pan. Note: A driver may notice any of the following symptoms before an engine failure: an oil leak under the vehicle, a smell of hot or burning oil, a knocking sound from the engine, reduced power or hesitation, a check engine light, and/or an oil pressure warning light.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)

Recall #: C0367 | Auxiliary Carbon Canister Install Recall Date: 2019 Nov 18

Recall Description

Issue: On certain vehicles, the evaporative canister may have a defective sponge that is too short in length causing charcoal dislodging to occur. This may reduce the effectiveness of the canister and result in emissions exceeding the prescribed standards. Corrective measures: Dealers will install an auxiliary canister on all affected vehicles.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)

Recall #: R0181 | Engine Control Module Reprogramming Recall Date: 2021 Sep 13

Recall Description

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects vehicles equipped with a 2.4 L MPI engine. For the Sonata model, only the Sonata Hybrid is affected by this campaign. All vehicles previously included in TC # 2021-033 are now part of this new campaign. Vehicles that were previously repaired under campaign R0181 (Transport Canada #2021-033) do not require this software update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)

Recall #: C0525 - LM | Underbody Corrosion Recall Date: 2023 Dec 04

Recall Description

Issue: Hyundai Auto Canada is conducting a Special Service Campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. In extreme cases, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)

Recall #: R0246-1 | Anti-lock Brake System (ABS) Module Recall Date: 2024 Apr 01

Recall Description

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai Canada recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Mar 31		Service Facility Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2011 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2012 Feb 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Feb 23		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Feb 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Mar 7	66,920 KM	Mobil 1 Lube Express Mission, British Columbia, Canada	Service Record	Vehicle serviced
2014 Apr 30	72,065 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2014 May 21		West Coast Toyota Pitt Meadows, British	Service Record	Vehicle serviced

KM8JUCAC3BU273881

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Columbia, Canada		
2014 May 23	73,692 KM	Maple Ridge Hyundai Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2014 May 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Dealer took registration of this vehicle while it was in inventory
2014 May 29	73,864 KM	Service Facility Pitt Meadows, British Columbia, Canada	Service Record	Vehicle serviced
2014 Oct 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2015 Oct 31		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jul 18		Insurance Records British Columbia, Canada	COLLISION	
2016 Jul 18		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2017 Mar 12		Insurance Records British Columbia, Canada	COLLISION	
2017 Mar 12		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Nov 11		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Dec 20		Insurance Records British Columbia, Canada	COLLISION	LEFT REAR SIDE
2018 Dec 20		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT REAR SIDE
2019 Mar 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jul 12		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0152
2019 Nov 18		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0367
2020 Mar 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

KM8JUCAC3BU273881

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jun 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2021 Sep 13		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0181
2022 Jan 22		Insurance Records British Columbia, Canada	Glass Record	\$726.42
2022 Jun 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2022 Aug 13	140,859 KM	Express Lube North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2023 Jun 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Aug 8	147,146 KM	Express Lube North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2023 Dec 4		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0525 - LM
2024 Apr 1		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0246-1
2024 Jun 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2024 Dec 2		Insurance Records British Columbia, Canada	COLLISION	
2025 Mar 18		Insurance Records British Columbia, Canada	COLLISION	LEFT REAR CORNER
2025 Mar 18		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT REAR CORNER
2025 Jun 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2025 Sep 19	163,954 KM	Supertech Auto North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2025 Sep 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black

KM8JUCAC3BU273881



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

